

CGT



8000Gs

18000Gs



	× mm× mm		r/min			Gs		mm	t/h	kW	
CGT- 3/5								1			0.37
2CGT- 3/5								2			0.37
3CGT- 3/5	300× 500	100× 500						3	0.8 1.0	0.75	0.55
4CGT- 3/5								4			0.55× 2
CGT- 4/8								1			0.55
2CGT- 4/8								2			0.75
3CGT- 4/8	400× 800	100× 800						3	1.2 2.0	1.10	0.75
4CGT- 4/8								4			0.75× 2
CGT- 5/10								1			0.55
2CGT- 5/10								2			0.75
3CGT- 5/10	500× 1000	100× 1000	30	17 82	4000	12000	0.1 2.0	3	2.0 3.5	1.50	0.75
4CGT- 5/10								4			0.75× 2
CGT- 5/12								1			0.75
2CGT- 5/12								2			1.10
3CGT- 5/12	500× 1200	100× 1200						3	4.0 7.0	2.20	1.10
4CGT- 5/12								4			1.10× 2
CGT- 6/15								1			0.75
2CGT- 6/15								2			1.50
3CGT- 6/15	600× 1500	100× 1500						3	7.0 10.0	4.00	1.50
4CGT- 6/15								4			1.50× 2

1.5 2.5

()

